


## **RESEARCH ARTICLE**

Available online at http://www.journalijdr.com



International Journal of Development Research Vol. 10, Issue, 09, pp. 40172-40174, September, 2020 https://doi.org/10.37118/ijdr.19994.09.2020



**OPEN ACCESS** 

# A MULTI-SCALE CANNY DETECTION TECHNIQUE FOR AUTOMATIC ASSESSMENT OF FATIGUE CRACKING USING MORPHOLOGICAL OPERATORS

## \*1Sai Suman, P., <sup>2</sup>Venkata Ramana, N. and <sup>3</sup>Sashidhar, C.

<sup>1</sup>Research Scholar, Civil Engineering Dept., JNTUA, Anantapuramu, A.P-515002 <sup>2</sup>Associate Professor, Civil Engineering Dept., UBDT CE, Davangere, Karnataka-577004 <sup>3</sup>Professor of Civil Engineering, Civil Engineering Dept., JNTUA, Anantapuramu, A.P-515002

### ARTICLE INFO

Article History: Received 22<sup>nd</sup> June 2020 Received in revised form 17<sup>th</sup> July 2020 Accepted 04<sup>th</sup> August 2020 Published online 29<sup>th</sup> September 2020

#### Key Words:

Fatigue Cracking; Digital Image Processing; Canny Detection; Logarithmic Transform; Morphological operators; Bilateral Filtering:

\*Corresponding author: Sai Suman, P,

### ABSTRACT

The maintenance of existing pavements with a good quality is one of the key challenges to the pavement engineers. The pavement condition monitoring and evaluation is a complex task to proceed for making decisions regarding the appropriate maintenance strategies. Generally, the Pavement Condition Evaluation involves in measuring the roughness, skidding index and pavement distresses. The fatigue cracking is one of the major distresses occurring in flexible pavements. The present research study focused on detecting the fatigue cracking using the Digital Image Processing (DIP). The image preprocessing techniques like linear-smoothing technique and bilateral filtering were used for removing the noise and background non-uniform illumination. Later, Canny's detection technique and morphological operators were used for enhancing the detection-accuracy. Finally, the resultant output was obtained via python programming and concluded that the proposed algorithm showed better results compared to the techniques without morphological operators.

**Copyright** © 2020, Sai Suman et al. This is an open access article distributed under the Creative Commons Attribution License, which permits unrestricted use, distribution, and reproduction in any medium, provided the original work is properly cited.

Citation: Sai Suman, P., Venkata Ramana, N. and Sashidhar, C. 2020. "A multi-scale canny detection technique for automatic assessment of fatigue cracking using morphological operators", International Journal of Development Research, 10, (09), 40172-40174.

# **INTRODUCTION**

Generally, the pavement distress assessment is important step in Pavement Management System. The pavement distresses can be evaluated directly or indirectly using manual or automatic methods respectively. The present study focused on evaluating the fatigue cracking. The fatigue cracking mainly occurs due to stiffer asphalt layers during the cold climates. The pavement is subjected to fatigue failure during its middle or late service life. It is necessary to recognize the microcracks or low-intensity fatigue cracking in order to reduce the cost of maintenance works. The concepts of image processing have been extensively used in automated pavement condition assessment. The previous studies adopted different techniques using curvelet, beamlet, ridgelet, wavelet transforms. The present study focused on detecting the fatigue cracking with the help of canny detection technique and morphological operators (dilation and erosion).

# THE STUDY METHODOLOGY

The present study involved in a series of algorithms for detecting the pavement cracks. Firstly, the images were collected using the line-scan cameras mounted on Network Survey Vehicle (NSV). Secondly, the collected BGR-colored imageswere converted in to gray scale images. Thirdly, the gaussian filtering technique was adopted for removing the background noise. Later, the logarithmic transform and bilateral filtering techniques were performed for achieving the uniform illumination. In addition to them, the Canny detection method was used for detecting the pavement cracks. Finally, the morphological closing operator was utilized to increase the performance of detecting the cracks and the resultant images were presented and conclusions were made.

**Image Acquisition System**: In this study, Hawkeye-2000 Network Survey Vehicle (NSV) developed by Indian Road Survey Management was used for collecting the pavement surface. This vehicle captured the images at an interval of 10m and a width coverage of 8m. The images were captured by using three front cameras mounted on NSV. The image of NSV used for present study is shown in following Figure 2.




Figure 1. The study approach for detecting the fatigue cracking




Figure 2. The Hawkeye 2000 Network Survey Vehicle

**Image Preprocessing:** A total of 80 images were selected for assessing the fatigue cracking. In the image preprocessing step, the colored images were converted in to gray scale images.

**Linear Filtering with Gaussian Blur:** The following Gaussian blur transform with linear filtering was adopted for initial denoising purpose.

$$GB[I]_{\mathbf{p}} = \sum_{\mathbf{q} \in \mathcal{S}} G_{\sigma}(\|\mathbf{p} - \mathbf{q}\|) \ I_{\mathbf{q}},$$

Where,

P represents the center position;

 $G_{\sigma}|p\text{-}q|$  represent the distance between center position and adjacent position considered

GB is Gaussian Blur;

 $G_{\sigma}\text{is}$  2-dimensional Gaussian Kernel and is defined by following equation

$$G_{\sigma}(x) = \frac{1}{2\pi \, \sigma^2} \, \exp\left(-\frac{x^2}{2 \, \sigma^2}\right)$$

**Bilateral Filtering:** The Bilateral Filter (BF) is also defined in terms of weighted average of pixels as similar to the Gaussian Blur. This filter is important in considering the variation in intensities and takes it into account for preserving the edges. Bilateral filtering is based on principle that "if two pixels occupy nearly spatial location and have similarity in photometric range, then that two pixels said to be close to each other". The bilateral filter is defined as follows:

$$BF[I]_{\mathbf{p}} = \frac{1}{W_{\mathbf{p}}} \sum_{\mathbf{q} \in \mathcal{S}} G_{\sigma_{s}}(\|\mathbf{p} - \mathbf{q}\|) \ G_{\sigma_{r}}(I_{\mathbf{p}} - I_{\mathbf{q}}) \ I_{\mathbf{q}}$$

Where,

W<sub>P</sub> is defined normalization factor as given below:

$$W_{\mathbf{p}} = \sum_{\mathbf{q} \in \mathcal{S}} G_{\sigma_{s}}(\|\mathbf{p} - \mathbf{q}\|) \ G_{\sigma_{r}}(I_{\mathbf{p}} - I_{\mathbf{q}})$$

Where,  $\sigma_s$  and  $\sigma_r$  are used for measuring the amount of filtering  $G\sigma_s$  and  $G\sigma_r$  are spatial and range Gaussians respectively.

**Canny Detection and Morphological closing:** The Canny detection method was developed by Canny in 1986. It is a multi-stage algorithm used for detecting the several edges in given images. The canny detection algorithm mainly composed of following five stages:

- Denoising,
- Measurement of Gradient,
- Non-Maximum Suppression,
- Dual Thresholding,
- Tacking the edge

In this study, a 5 by 5 kernel was used for canny detection and morphological closing. Generally, morphological operation involves in two stages such as dilation and erosion. The closing morphology was adopted for enhancing the accuracy in detecting the fatigue cracks. The input and resultant images are shown in following Figure 3.




Figure 3. The input (left side-image) and output images (right side)

In this study, a total of 80 images were tested and the corresponding accuracy was computed. The collected 80 images composed of the images with fatigue cracking (60 images) and without fatigue cracking (20 images). The results of proposed algorithm are shown in following Table 1. The accuracy was determined by using following equation:

$$Accuracy = \frac{\text{Total number of images correctly predicted}}{\text{Total number of images tested}} \times 100$$

 $Accuracy = \frac{58 + 19}{60 + 20} \times 100 = 96.25\%$ 

Table 1. The results of detecting the fatigue cracking

S. No	Images with	Images without
	Fatigue	Fatigue
Detected Correctly	58	19
Detected Wrongly	2	1
Total	60	20

#### Summary

The results showed that the enhanced accuracy in detecting the fatigue cracking as compared to the Canny detection without morphological closing operator. In this study, a total of 80 images were tested and the fatigue crackings were detected with an accuracy of 96.25%.

### REFERENCES

- Capuruço, R. A. C., Tighe, S. L., Ningyuan, L., and Kazmierowski, T. 2006. "Performance evaluation of sensor- And image-based technologies for automated pavement condition surveys." *Transportation Research Record*, (1968), 47–52.
- Hamdallah, M. E., and Srouji, A. F. 2018. 8th International Conference on Engineering, Project, and Product Management (EPPM 2017). Springer International Publishing.
- Liu, F., Xu, G., Yang, Y., Niu, X., and Pan, Y. 2008. "Novel approach to pavement cracking automatic detection based on segment extending." *Proceedings - 2008 International Symposium on Knowledge Acquisition and Modeling*, *KAM 2008*, 610–614.

- Mustaffar, M., Ling, T. C., and Puan, O. C. 2007. "Automated pavement imaging program (APIP) for pavement cracks classification and quantification." *Malaysian Journal of Civil Engineering*, 19(1), 1–16.
- Oliveira, H., and Correia, P. L. 2009. "Evaluation of Preprocessing in Road Pavement Image Analysis." *Conf. on Telecommunications* -*ConfTele*, 2–5.
- Ouyang, A., and Wang, Y. 2012. "Edge detection in pavement crack image with beamlet transform." Proceedings of the 2nd International Conference on Electronic and Mechanical Engineering and Information Technology, EMEIT 2012, 2036–2039.
- Ouyang, A., Dong, Q., Wang, Y., and Liu, Y. 2014. "The classification of pavement crack image based on beamlet algorithm." *IFIP Advances in Information and Communication Technology*, 420, 129–137.
- Paris, S., Kornprobst, P., Tumblin, J., and Durand, F. 2008. "A gentle introduction to bilateral filtering and its applications." ACM SIGGRAPH 2008 Classes, (c), 1.
- Salvatore Cafiso, A. D. G., and Battiato, S. (2006). "Evaluation of Pavement Surface Distress Using Digital Image Collection and Analysis." Seventh International Congress on Advances in Civil Engineering. Istanbul, Turkey, (January), 1–10.
- Wang, K. C. P., Li, Q., and Gong, W. 2007. "Wavelet-based pavement distress image edge detection with a trous algorithm." *Transportation Research Record*, (2024), 73– 81.
- Wei, W., Ding, M., and Wang, Q. 2005. "A binary image enhancement and recognition approach in crack detection using exploring agents." *Electronic Imaging and Multimedia Technology IV*, 5637, 287.
- Xiao, W., Yan, X., and Zhang, X. (n.d.). "Classification Based on DENSITY-Based Neural." 685–686.
- Zhang, K., Cheng, H. D., and Zhang, B. 2018. "Unified Approach to Pavement Crack and Sealed Crack Detection Using Preclassification Based on Transfer Learning." *Journal of Computing in Civil Engineering*, 32(2), 1–12.

\*\*\*\*\*\*